General Environmental Incident Summary

Incident: 4132 Date/Time Notice: 6/13/2016 0747 DEM Incident No:

Responsible Party: Otter Tail Power Company

Date Incident:6/12/2016Time Incident:19:00Duration:County:BarnesTwp:138Rng:56Sec:18Qtr:Lat:46.76411Long:-97.78877Method:Interpolation from map

Location Description: 445 2nd Avenue Fingal, ND

Submitted By: Paul Vukonich Affiliation:

Address: 215 South Cascade Street

City: Fergus Falls State: MN Zip: 56538-0496

Received By:

Contact Person: Paul Vukonich

215 South Cascade Street Fergus Falls, MN 56538-0496

Distance Nearest Occupied Building: Release Contained: Yes

Type of Incident: Transformer oil spill

Description of Released Contaminant: Transformer oil potentially containing PCBs

Volume Spilled: 25.00 gallons Ag Related: No

EPA Extremely Hazardous Substance: No Reported to NRC: No

Cause of Incident:

Bottom of transformer rusted out

Risk Evaluation:

PCBs may be presented, but the area has been cordoned off.

of Fatalities: # of Injuries: Affected Medium: 03 - soil

Potential Environmental Impacts:

Oil spill occurred on grassy area. Grass will die. Potential surface soil contamination.

Action Taken or Planned:

Transformer removed. Area cordoned off, oil sample collected and sent in to laboratory for PCB analysis. Field test confirmed PCBs may be present.

Wastes Disposal Location:

Agencies Involved:

Updates

Date: 6/13/2016 Status: Correspondence Author: Tintes Schiwal, Emily

Updated Volume:

Notes:

I contacted the staff of Ottertail requesting more detailed information about the situation. I will update this as I acquire information.

Date: 6/13/2016 Status: Reviewed - Assigned to NDDoH Division Author: Souder, Taylor

Updated Volume:

Notes:

Forwarded to the Division of Waste Management within the NDDoH.